

Advt. No. IITH/2023/NF/15

Question Paper Code:

Application Number of the Candidate	
Name of the Post: Junior Technical Superintendent -Central Workshop (12	2.2) Pay Level: 06
Date & Time of the Exam: 6 Dec 2023, 9.00 am	Duration: 01 hr. 30 min

Scheme of the Exam:

Topic	Number of Question	Marks
General English (Communication Skills)	10	10
General Arithmetic		
Reasoning		
Work Related Topics	40	40


Instructions to fill the responses in the OMR answer sheet:

- 1. Candidate must write his/her application number in the designated box on the top of OMR answer sheet.
- 2. Candidates must write the post code and Question paper code in the designated boxes on the top of OMR answer sheet.
- 3. Candidates must sign in the box provided in the OMR answer sheet.
- 4. Each answer sheet must be signed by the invigilator in the space printed in the OMR answer sheet.
- 5. Only one response to be selected & marked. In case more than one response is marked for a single question or no response is marked for a question, no marks will be awarded for that question.
- 6. Partially filled circles shall not be considered as responses.
- 7. Erasing or changing of answer is not allowed.
- 8. No negative marking
- 9. Candidate must use Blue/Black ball point pen to fill his/her responses.
- 10. Rough work should not be done on the OMR answer sheet.
- 11. Candidates can use the designated page(s) of the question booklet for the purpose of rough work.

1	Choose suitable "wh" word for the given sentence_ " are you angry?"
Α	Which
В	Why
С	Who
D	What
2	Which one is NOT a vowel?
Α	A
В	E
С	0
D	Z
3	Choose the correct tense of the verb. "I music next year."
Α	learn
В	am learning
С	will learn
D	learnt
4	Fill in the blank with comparative adjectives. "Your knife is than mine".
4 A	Fill in the blank with comparative adjectives. "Your knife is than mine". sharp
-	
Α	sharp
A B	sharp sharper
A B C	sharp sharper blunt
A B C	sharp sharper blunt
A B C D	sharp sharper blunt thick
A B C D	sharp sharper blunt thick Fill in the blank with correct word "They good friends"
A B C D	sharp sharper blunt thick Fill in the blank with correct word "They good friends" is
A B C D	sharper blunt thick Fill in the blank with correct word "They good friends" is am
A B C D	sharper blunt thick Fill in the blank with correct word "They good friends" is am were
A B C D	sharper blunt thick Fill in the blank with correct word "They good friends" is am were
A B C D	sharper blunt thick Fill in the blank with correct word "They good friends" is am were was
A B C D 5 A B C D	sharper blunt thick Fill in the blank with correct word "They good friends" is am were was What are fundamental units?
A B C D 5 A B C D	sharper blunt thick Fill in the blank with correct word "They good friends" is am were was What are fundamental units? Length, Mass, Volume

7	What is the unit of mass?
Α	grams
В	pounds
С	tonnes
D	All of the above

8	What is the x value for $x^2 + 66 = 102$?
Α	10
В	8
С	6
D	4



10	How many days will a mechanic take to assemble 64 machines if he assembles 8
	machines in 4 days?
Α	8 days
В	16 days
С	24 days
D	32 days

11	The quality control allows at the most 0.4% defective parts. How many defective parts
	can be allowed in a production of 5000 parts?
Α	10
В	20
С	100
D	200

12	Which code is used for "Circular interpolation clockwise direction"?
Α	G01
В	G02
С	G03
D	G00

13	What is the purpose of a circlip
Α	Deburring hole ends
В	Accommodating circlipping screws
С	To accommodate socket head screws
D	To lock the position


14	A shaft whose upper deviation is zero is called a basic shaft, which one of the following letters indicates a basic shaft?
Α	е
В	f
С	g
D	h


15	There are two types of milling processes based on the direction of cutter rotation and
	work feed direction. Which of the following represents the down-milling operation?
Α	The work is fed in the same direction as the rotation of the cutter
В	Chip removal starts at the thinnest part
С	The work is fed against direction of the cutter rotation
D	None of the above

16	Why the balancing weight is provided in the milling fixture?
Α	To guide tool
В	To balance the tool
С	To eliminate backlash
D	None of the above

17	Which gauge is used to check the gap between the mating parts?
Α	Slip gauge
В	Plug gauge
С	Feeler gauge
D	Radius gauge
10	Why is the consoling process consist out in steel 2
18	Why is the annealing process carried out in steel?
Α	To add cutting ability To relieve strain and stress
В	
С	To decrease the hardness
D	All of the above
19	Which of the following material has the highest carbon percentage?
Α	Mild steel
В	EN8
С	EN24
D	EN31
20	Which property is necessary for the material of slip gauge block?
A	Hardness
В	Thermal expansion
C	Wear resistance
D	All of the above
	All of the above
21	A woodruff key is should be used for
Α	Non tapering shafts
В	Tapering shafts
С	Serrated shafts
D	Splined shaft
22	The automatic feeding of the tool in a conventional lathe is powered by
Α	Lead screw
В	Feed rod
С	Split nut
D	All of the above
<u> </u>	<u>-</u>

23	What is the pitch of multi start thread?
Α	Lead / no of starts
В	Lead x no of starts
С	Lead x major diameter
D	Leadz x minor diameter





26	What is the negative of the ratio of the strain in lateral dimension to the longitudinal
	strain?
Α	Stress
В	Strain
С	Poisson's ratio
D	Factor of safety


27	How much strain is developed in an iron rod of 10 metre length that gets elongated by 1
	cm, if a force of 100 kg is applied at one end?
Α	0.1
В	0.01
С	0.001
D	0.0001
20	Which I are founding on he and I and I are and MI a 2
28	Which type of machines can be used to make a woodruff key?
A	Lathe and Shaper
В	Lathe and wire-cut EDM
С	Lathe and milling
D	All of the above
29	Which of the below is an important part of a CNC machine?
Α	ATC
В	ATM
С	UTM
D	UTC
30	When acceleration is, velocity of a particle is constant.
	la caracteristica di caracteri
Α	constant but non zero
В	Zero
В	Zero
B C	Zero Minimum
B C D	Zero Minimum Maximum
B C D	Zero Minimum Maximum Which motor does not controls the axes of the table of a CNC machine?
B C D	Zero Minimum Maximum Which motor does not controls the axes of the table of a CNC machine? Air motor
B C D	Zero Minimum Maximum Which motor does not controls the axes of the table of a CNC machine? Air motor DC series motor
B C D	Zero Minimum Maximum Which motor does not controls the axes of the table of a CNC machine? Air motor DC series motor Hydraulic motor
B C D	Zero Minimum Maximum Which motor does not controls the axes of the table of a CNC machine? Air motor DC series motor
B C D	Zero Minimum Maximum Which motor does not controls the axes of the table of a CNC machine? Air motor DC series motor Hydraulic motor
B C D	Zero Minimum Maximum Which motor does not controls the axes of the table of a CNC machine? Air motor DC series motor Hydraulic motor
B C D	Zero Minimum Maximum Which motor does not controls the axes of the table of a CNC machine? Air motor DC series motor Hydraulic motor All of the above
B C D	Zero Minimum Maximum Which motor does not controls the axes of the table of a CNC machine? Air motor DC series motor Hydraulic motor All of the above Which code describes the auxiliary function of a CNC machine?
31 A B C D	Zero Minimum Maximum Which motor does not controls the axes of the table of a CNC machine? Air motor DC series motor Hydraulic motor All of the above Which code describes the auxiliary function of a CNC machine? N - words
31 A B C D	Zero Minimum Maximum Which motor does not controls the axes of the table of a CNC machine? Air motor DC series motor Hydraulic motor All of the above Which code describes the auxiliary function of a CNC machine? N - words F - words

33	What is "G40" in program?
Α	Cutter radius compensation lift
В	Cutter compensation cancel
С	Cutter radius compensation right
D	Cutter offset outside complex

34	What does 1.25 stands for a metric thread designated as M16 x 1.25?
Α	Major dia of thread
В	Minor dia of thread
С	Pitch of the thread
D	Depth of thread

35	Calculate the driven gear to cut 4 mm pitch thread on a job using a lathe having lead
	screw of 4mm pitch with driver gear 30 teeth?
Α	30
В	60
С	90
D	120

36	What is removing dull grain in order to make a grinding wheel sharp?
Α	Loading
В	Glazing
С	Sharpening
D	None of the above



38	When two resistors of resistance R are connected in series, their effective resistance is
Α	R/2
В	R
С	3R/2
D	2R

39	What is the name of bearing?
Α	Needle bearing
В	Thrust ball bearing
С	Taper roller bearing
D	Angular contact ball bearing


40	Which method is used to avoid machine collision in VMC during initial practice?
Α	Simulation
В	Auto cycle
С	Manual method
D	Jog method

41	Which of the following is a typical composition of high speed steel?
Α	18% Vanadium, 4% Chromium and 1% Tungsten
В	18% Chromium, 4% Tungsten and 1% Vanadium
С	18% Tungsten, 4% Vanadium and 1% Chromium
D	18% Tungsten, 4% Chromium and 1% Vanadium


42	Knurling is a	operation.
Α	Cutting	
В	Rolling	
С	Forming	
D	Turning	

43	Which of the forming can be done on a lathe?
Α	Roll forming
В	Upsetting
С	Spin forming
D	Deep drawing

44	A component distorts after welding due to
Α	Residual stresses
В	Blow holes
С	Internal cracks
D	Internal cavities



46	In a CNC Program Block
	N10 G02 G91 X 52 Z 25
	G02 represents:
Α	Circular clockwise interpolation
В	Linear interpolation
С	Incremental command
D	Absolute command



48	Which mode is used to enter part program in VMC?
Α	EDIT
В	JOG
С	MDI
D	Auto

49	What is the ratio between ultimate stress to working stress?
Α	Bulk modulus
В	Young's modulus
С	Factor of safety
D	Modulus of rigidity

50	MO6 represents the following instruction in CNC programing
Α	Program stop
В	Tool change
С	Coolant on
D	Spindle on